

WELL ABANDONMENT RECORD
Maine Department of Environmental Protection
Bureau of Remediation and Waste Management

MW-21

<p>1. Date of Abandonment: <u>4/13</u></p> <p>2. Abandonment Contractor: <u>North-Henry Test Boring</u> Company <u>Mike Nadreau</u> Printed Name of Individual Abandoning Well</p> <p>3. Well Location: <u>Tenney Hill Road</u> Address <u>Cumberland</u> County <u>Casco</u> Nearest Town Latitude (D,M,S or DD format) Longitude</p> <p>4. Well Type: <input type="checkbox"/> direct push <input checked="" type="checkbox"/> drilled</p> <p>5. Well Use: <input checked="" type="checkbox"/> monitoring <input type="checkbox"/> residential <input type="checkbox"/> industrial <input type="checkbox"/> injection <input type="checkbox"/> recovery <input type="checkbox"/> geotechnical</p> <p>6. Reason for abandonment: <u>No longer in use</u></p> <p>7. Are boring logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p> <p>8. Are well construction logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p>	<p>9. Well Depth (ft): <u>52</u></p> <p>10. Boring Diameter (in): <u>4</u></p> <p>11. Riser/Casing Diameter (in): <u>2</u></p> <p>12. Type of Casing: <input type="checkbox"/> steel <input checked="" type="checkbox"/> PVC</p> <p>13. Was any casing removed? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, length removed (ft.): <u>52</u></p> <p>14. Was well abandoned in place? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, was casing perforated? <input type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>15. Abandonment Material: <input checked="" type="checkbox"/> bentonite grout <input type="checkbox"/> dry bentonite <input type="checkbox"/> cement grout <input type="checkbox"/> native soil</p> <p>16. Quantity of Material Used: # of bags <u>1.5 Bags</u>, or cubic feet _____</p> <p>17. Explain Method of Material Placement: <u>PVC Removed</u> <u>Redrilled hole using 4" casing</u> <u>pumped Grout thru</u> <u>d-111 rods</u></p> <p>18. Signature of Person Abandoning the Well: <u>[Signature]</u></p>
--	---


WELL ABANDONMENT RECORD
Maine Department of Environmental Protection
Bureau of Remediation and Waste Management

MW-20A

<p>1. Date of Abandonment: <u>4/13</u></p> <p>2. Abandonment Contractor: <u>No-Henry Test Boring</u> Company <u>Mike Nadreau</u> Printed Name of Individual Abandoning Well</p> <p>3. Well Location: <u>Tenney Hill Road</u> Address <u>Cumtucket</u> County <u>Casco</u> Nearest Town Latitude (D,M,S or DD format) Longitude</p> <p>4. Well Type: <input type="checkbox"/> direct push <input checked="" type="checkbox"/> drilled</p> <p>5. Well Use: <input checked="" type="checkbox"/> monitoring <input type="checkbox"/> residential <input type="checkbox"/> industrial <input type="checkbox"/> injection <input type="checkbox"/> recovery <input type="checkbox"/> geotechnical</p> <p>6. Reason for abandonment: <u>No longer in use</u></p> <p>7. Are boring logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p> <p>8. Are well construction logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p>	<p>9. Well Depth (ft): <u>72</u></p> <p>10. Boring Diameter (in): <u>4</u></p> <p>11. Riser/Casing Diameter (in): <u>2</u></p> <p>12. Type of Casing: <input type="checkbox"/> steel <input checked="" type="checkbox"/> PVC</p> <p>13. Was any casing removed? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, length removed (ft.): _____</p> <p>14. Was well abandoned in place? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, was casing perforated? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>15. Abandonment Material: <input checked="" type="checkbox"/> bentonite grout <input type="checkbox"/> dry bentonite <input type="checkbox"/> cement grout <input type="checkbox"/> native soil</p> <p>16. Quantity of Material Used: # of bags <u>1 Bag</u>, or cubic feet _____</p> <p>17. Explain Method of Material Placement: <u>Traverse pumped Grout</u> <u>from bottom of PVC</u></p> <p>18. Signature of Person Abandoning the Well: <u>[Signature]</u></p>
--	--


WELL ABANDONMENT RECORD
Maine Department of Environmental Protection
Bureau of Remediation and Waste Management

MW-18B

<p>1. Date of Abandonment: <u>4/13</u></p> <p>2. Abandonment Contractor: <u>Nor-Henry Test Boring</u> Company <u>Mike Nadreau</u> Printed Name of Individual Abandoning Well</p> <p>3. Well Location: <u>Tenney Hill Road</u> Address <u>Cumberland</u> County <u>Casco</u> Nearest Town Latitude (D,M,S or DD format) Longitude</p> <p>4. Well Type: <input type="checkbox"/> direct push <input checked="" type="checkbox"/> drilled</p> <p>5. Well Use: <input checked="" type="checkbox"/> monitoring <input type="checkbox"/> residential <input type="checkbox"/> industrial <input type="checkbox"/> injection <input type="checkbox"/> recovery <input type="checkbox"/> geotechnical</p> <p>6. Reason for abandonment: <u>No longer in use</u></p> <p>7. Are boring logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p> <p>8. Are well construction logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p>	<p>9. Well Depth (ft): <u>31</u></p> <p>10. Boring Diameter (in): <u>4</u></p> <p>11. Riser/Casing Diameter (in): <u>1</u></p> <p>12. Type of Casing: <input type="checkbox"/> steel <input checked="" type="checkbox"/> PVC</p> <p>13. Was any casing removed? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, length removed (ft.): <u>30'</u></p> <p>14. Was well abandoned in place? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, was casing perforated? <input type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>15. Abandonment Material: <input checked="" type="checkbox"/> bentonite grout <input type="checkbox"/> dry bentonite <input type="checkbox"/> cement grout <input type="checkbox"/> native soil</p> <p>16. Quantity of Material Used: # of bags <u>1/2 bag</u>, or cubic feet _____</p> <p>17. Explain Method of Material Placement: <u>Transfer Pump Grout</u> <u>in open hole</u></p> <p>18. Signature of Person Abandoning the Well: </p>
--	--

WELL ABANDONMENT RECORD
Maine Department of Environmental Protection
Bureau of Remediation and Waste Management

MW-18A

<p>1. Date of Abandonment: <u>4/13</u></p> <p>2. Abandonment Contractor: <u>Nor-Henn Test Boring</u> Company <u>Mike Nadreau</u> Printed Name of Individual Abandoning Well</p> <p>3. Well Location: <u>Tenney Hill Road</u> Address <u>Cumberland</u> County <u>Casco</u> Nearest Town Latitude (D,M,S or DD format) Longitude</p> <p>4. Well Type: <input type="checkbox"/> direct push <input checked="" type="checkbox"/> drilled</p> <p>5. Well Use: <input checked="" type="checkbox"/> monitoring <input type="checkbox"/> residential <input type="checkbox"/> industrial <input type="checkbox"/> injection <input type="checkbox"/> recovery <input type="checkbox"/> geotechnical</p> <p>6. Reason for abandonment: <u>No longer in use</u></p> <p>7. Are boring logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p> <p>8. Are well construction logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p>	<p>9. Well Depth (ft): <u>80</u></p> <p>10. Boring Diameter (in): <u>4</u></p> <p>11. Riser/Casing Diameter (in): <u>1</u></p> <p>12. Type of Casing: <input type="checkbox"/> steel <input checked="" type="checkbox"/> PVC</p> <p>13. Was any casing removed? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, length removed (ft.): <u>80</u></p> <p>14. Was well abandoned in place? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, was casing perforated? <input type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>15. Abandonment Material: <input checked="" type="checkbox"/> bentonite grout <input type="checkbox"/> dry bentonite <input type="checkbox"/> cement grout <input type="checkbox"/> native soil</p> <p>16. Quantity of Material Used: # of bags <u>1 bag</u>, or cubic feet _____</p> <p>17. Explain Method of Material Placement: <u>Tremie Grout</u> <u>In open hole</u></p> <p>18. Signature of Person Abandoning the Well: </p>
---	--

WELL ABANDONMENT RECORD
Maine Department of Environmental Protection
Bureau of Remediation and Waste Management

MW-132

<p>1. Date of Abandonment: <u>4/13</u></p> <p>2. Abandonment Contractor: <u>North-Henry Test Boring</u> Company <u>Mike Nadolan</u> Printed Name of Individual Abandoning Well</p> <p>3. Well Location: <u>Tenney Hill Road</u> Address <u>Cumberland</u> County <u>Casco</u> Nearest Town Latitude (D,M,S or DD format) Longitude</p> <p>4. Well Type: <input type="checkbox"/> direct push <input checked="" type="checkbox"/> drilled</p> <p>5. Well Use: <input checked="" type="checkbox"/> monitoring <input type="checkbox"/> residential <input type="checkbox"/> industrial <input type="checkbox"/> injection <input type="checkbox"/> recovery <input type="checkbox"/> geotechnical</p> <p>6. Reason for abandonment: <u>No longer in use</u></p> <p>7. Are boring logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p> <p>8. Are well construction logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p>	<p>9. Well Depth (ft): <u>91</u></p> <p>10. Boring Diameter (in): <u>4</u></p> <p>11. Riser/Casing Diameter (in): <u>1</u></p> <p>12. Type of Casing: <input type="checkbox"/> steel <input checked="" type="checkbox"/> PVC</p> <p>13. Was any casing removed? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, length removed (ft.): <u>91</u></p> <p>14. Was well abandoned in place? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, was casing perforated? <input type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>15. Abandonment Material: <input checked="" type="checkbox"/> bentonite grout <input type="checkbox"/> dry bentonite <input type="checkbox"/> cement grout <input type="checkbox"/> native soil</p> <p>16. Quantity of Material Used: # of bags <u>1 Bag</u>, or cubic feet _____</p> <p>17. Explain Method of Material Placement: <u>Terra Pregel Grout</u> <u>in open hole</u></p> <p>18. Signature of Person Abandoning the Well: _____</p>
--	---


WELL ABANDONMENT RECORD
Maine Department of Environmental Protection
Bureau of Remediation and Waste Management

MW-13Y

<p>1. Date of Abandonment: <u>4/13</u></p> <p>2. Abandonment Contractor: <u>North-Henry Test Boring</u> Company <u>Mike Nadreau</u> Printed Name of Individual Abandoning Well</p> <p>3. Well Location: <u>Tenney Hill Road</u> Address <u>Cumberland</u> County <u>Casco</u> Nearest Town Latitude (D,M,S or DD format) Longitude</p> <p>4. Well Type: <input type="checkbox"/> direct push <input checked="" type="checkbox"/> drilled</p> <p>5. Well Use: <input checked="" type="checkbox"/> monitoring <input type="checkbox"/> residential <input type="checkbox"/> industrial <input type="checkbox"/> injection <input type="checkbox"/> recovery <input type="checkbox"/> geotechnical</p> <p>6. Reason for abandonment: <u>No longer in use</u></p> <p>7. Are boring logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p> <p>8. Are well construction logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p>	<p>9. Well Depth (ft): <u>56</u></p> <p>10. Boring Diameter (in): <u>4</u></p> <p>11. Riser/Casing Diameter (in): <u>1</u></p> <p>12. Type of Casing: <input type="checkbox"/> steel <input checked="" type="checkbox"/> PVC</p> <p>13. Was any casing removed? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, length removed (ft.): <u>56</u></p> <p>14. Was well abandoned in place? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, was casing perforated? <input type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>15. Abandonment Material: <input checked="" type="checkbox"/> bentonite grout <input type="checkbox"/> dry bentonite <input type="checkbox"/> cement grout <input type="checkbox"/> native soil</p> <p>16. Quantity of Material Used: # of bags <u>1 Bag</u>, or cubic feet _____</p> <p>17. Explain Method of Material Placement: <u>Transfer pump Grout</u> <u>In open hole</u></p> <p>18. Signature of Person Abandoning the Well: <u>[Signature]</u></p>
--	---

WELL ABANDONMENT RECORD
Maine Department of Environmental Protection
Bureau of Remediation and Waste Management

GP-44

<p>1. Date of Abandonment: <u>4/13</u></p> <p>2. Abandonment Contractor: <u>North-Henry Test Boring</u> Company <u>Mike Nadreau</u> Printed Name of Individual Abandoning Well</p> <p>3. Well Location: <u>Tenney Hill Road</u> Address <u>Cumberland</u> County <u>Casco</u> Nearest Town Latitude (D,M,S or DD format) Longitude</p> <p>4. Well Type: <input checked="" type="checkbox"/> direct push <input type="checkbox"/> drilled</p> <p>5. Well Use: <input checked="" type="checkbox"/> monitoring <input type="checkbox"/> residential <input type="checkbox"/> industrial <input type="checkbox"/> injection <input type="checkbox"/> recovery <input type="checkbox"/> geotechnical</p> <p>6. Reason for abandonment: <u>No longer in use</u></p> <p>7. Are boring logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p> <p>8. Are well construction logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p>	<p>9. Well Depth (ft): <u>9</u></p> <p>10. Boring Diameter (in): <u>2</u></p> <p>11. Riser/Casing Diameter (in): <u>1</u></p> <p>12. Type of Casing: <input type="checkbox"/> steel <input checked="" type="checkbox"/> PVC</p> <p>13. Was any casing removed? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, length removed (ft.): <u>9</u></p> <p>14. Was well abandoned in place? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, was casing perforated? <input type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>15. Abandonment Material: <input type="checkbox"/> bentonite grout <input checked="" type="checkbox"/> dry bentonite <input type="checkbox"/> cement grout <input type="checkbox"/> native soil</p> <p>16. Quantity of Material Used: # of bags <u>1/2 Bag</u>, or cubic feet _____</p> <p>17. Explain Method of Material Placement: <u>Slowly Placed Chgs</u> <u>From Surface</u></p> <p>18. Signature of Person Abandoning the Well: </p>
--	--

WELL ABANDONMENT RECORD
Maine Department of Environmental Protection
Bureau of Remediation and Waste Management

6P-30

<p>1. Date of Abandonment: <u>4/13</u></p> <p>2. Abandonment Contractor: <u>Nor-Henn Test Boring</u> Company <u>Mike Nadreau</u> Printed Name of Individual Abandoning Well</p> <p>3. Well Location: <u>Tenney Hill Road</u> Address <u>Cumberland</u> County <u>Casco</u> Nearest Town Latitude (D,M,S or DD format) Longitude</p> <p>4. Well Type: <input checked="" type="checkbox"/> direct push <input type="checkbox"/> drilled</p> <p>5. Well Use: <input checked="" type="checkbox"/> monitoring <input type="checkbox"/> residential <input type="checkbox"/> industrial <input type="checkbox"/> injection <input type="checkbox"/> recovery <input type="checkbox"/> geotechnical</p> <p>6. Reason for abandonment: <u>No longer in use</u></p> <p>7. Are boring logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p> <p>8. Are well construction logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p>	<p>9. Well Depth (ft): <u>5</u></p> <p>10. Boring Diameter (in): <u>2</u></p> <p>11. Riser/Casing Diameter (in): <u>1</u></p> <p>12. Type of Casing: <input type="checkbox"/> steel <input checked="" type="checkbox"/> PVC</p> <p>13. Was any casing removed? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, length removed (ft.): <u>5'</u></p> <p>14. Was well abandoned in place? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, was casing perforated? <input type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>15. Abandonment Material: <input type="checkbox"/> bentonite grout <input checked="" type="checkbox"/> dry bentonite <input type="checkbox"/> cement grout <input type="checkbox"/> native soil</p> <p>16. Quantity of Material Used: # of bags <u>1/4 Bag</u>, or cubic feet _____</p> <p>17. Explain Method of Material Placement: <u>Slowly Placed Chgs</u> <u>From Surface</u></p> <p>18. Signature of Person Abandoning the Well: <u>[Signature]</u></p>
---	---

WELL ABANDONMENT RECORD
Maine Department of Environmental Protection
Bureau of Remediation and Waste Management

GP-26

<p>1. Date of Abandonment: <u>4/13</u></p> <p>2. Abandonment Contractor: <u>Nor-Henn Test Bury</u> Company <u>Mike Nadreau</u> Printed Name of Individual Abandoning Well</p> <p>3. Well Location: <u>Tenney Hill Road</u> Address <u>Cumberland</u> County <u>Casco</u> Nearest Town Latitude (D,M,S or DD format) Longitude</p> <p>4. Well Type: <input checked="" type="checkbox"/> direct push <input type="checkbox"/> drilled</p> <p>5. Well Use: <input checked="" type="checkbox"/> monitoring <input type="checkbox"/> residential <input type="checkbox"/> industrial <input type="checkbox"/> injection <input type="checkbox"/> recovery <input type="checkbox"/> geotechnical</p> <p>6. Reason for abandonment: <u>No longer in use</u></p> <p>7. Are boring logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p> <p>8. Are well construction logs available? <input type="checkbox"/> Yes, attached <input type="checkbox"/> No</p>	<p>9. Well Depth (ft): <u>5</u></p> <p>10. Boring Diameter (in): <u>2</u></p> <p>11. Riser/Casing Diameter (in): <u>1</u></p> <p>12. Type of Casing: <input type="checkbox"/> steel <input checked="" type="checkbox"/> PVC</p> <p>13. Was any casing removed? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, length removed (ft.): <u>5'</u></p> <p>14. Was well abandoned in place? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, was casing perforated? <input type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>15. Abandonment Material: <input type="checkbox"/> bentonite grout <input checked="" type="checkbox"/> dry bentonite <input type="checkbox"/> cement grout <input type="checkbox"/> native soil</p> <p>16. Quantity of Material Used: # of bags <u>1/4 Bag</u>, or cubic feet _____</p> <p>17. Explain Method of Material Placement: <u>Slowly Placed C Hps</u> <u>from surface</u></p> <p>18. Signature of Person Abandoning the Well: <u>[Signature]</u></p>
---	--